

SALHC1349SA654516

| Completed Services | Parts Cost |
|---|-------------------|
| Epsom Green Exterior Paint Job | \$ 1,750.00 |
| Rebuilt ZF 4HP Transmission Installed, Mated to Engine/T case | \$ 2,975.95 |
| Plug Wire Set | \$ 149.00 |
| Coolant Resovior | \$ 40.00 |
| Genuine Cooling hoses | \$ 349.00 |
| Refinished wood trim (skateboard) | \$ 200.00 |
| Idle air control valve | \$ 200.00 |
| Mud flaps (4) | \$ 100.00 |
| New Used Drivers Seat | \$ 400.00 |
| Seat ECU Refinished | \$ 400.00 |
| NRP Exhaust Complete | \$ 1,800.00 |
| 2" Terrafirma Lift Kit | \$ 600.00 |
| Kahn Rims, BF Goodrich Tires Mounted Balanced (5) | \$ 5,121.00 |
| Liftgate Assembly | \$ 800.00 |
| Transfer Box LT230 instsalled, mated to transmission | \$ 500.00 |
| Performance ECU installed | \$ 459.00 |
| Waxoyl Service (4 seasons) | \$ 350.00 |
| New Decals | \$ 360.00 |
| Oil Change and Filters | \$ 250.00 |
| Valve Cover Service- Valve Covers Polished, Tune up | \$ 100.00 |
| Paint Floors | \$ 50.00 |
| Paint Underbody | \$ 200.00 |
| Suspension Bushings | \$ 500.00 |
| New Used Carpet | \$ 750.00 |
| Buff and Polish Exterior | \$ 100.00 |
| Alternator 120 Amp | \$ 459.00 |
| Starter | \$ 219.00 |
| All new fluids | \$ 200.00 |
| Liftgate Tabs | \$ 69.00 |
| Custom Car Cover | \$ 500.00 |
| Refinished Headliner | \$ 1,000.00 |
| Brake Service | \$ 625.00 |
| Rear Rubber U-Joint | \$ 70.00 |
| Rear Carpet transition | \$ 100.00 |
| HID Lights | \$ 250.00 |
| New Fuel Pump | \$ 289.00 |
| Hella Vision Plus Headlamps | \$ 110.00 |
| Windscreen Seal Kit | \$ 395.00 |

| | |
|-------------------|---------------------|
| Heated Windscreen | \$ 1,250.00 |
| Total | \$ 24,039.95 |

Additional Options

| | |
|--|--------------|
| Custom Sheepskin Seat Covers | \$ 1,200.00 |
| Bilstein Suspension Kit (Bilstein Shocks, Genuine Coils) | \$ 800.00 |
| Congleton Service ICEBOX Radiator | \$ 1,360.00 |
| Congleton Service Cooler Line Kit | \$ 294.00 |
| Congleton Service Oil Cooler 7 Row | \$ 249.00 |
| Paint Inside of Doors | \$ 200.00 |
| 5.0 Liter Engine Swap | \$ 13,287.00 |
| Factory Style Borg Warner Transfer Box | \$ 2,399.00 |

Labor Cost

\$ 5,000.00
\$ 1,440.00
\$ 90.00
\$ 90.00
\$ 360.00
\$ 90.00
\$ 90.00
\$ 360.00
\$ 180.00
\$ 180.00
\$ 270.00
\$ 740.00
\$ 90.00
\$ 360.00
\$ 1,240.00
\$ 90.00
\$ 740.00
\$ 180.00
\$ 90.00
\$ 1,440.00
\$ 540.00
\$ 740.00
\$ 1,080.00
\$ 360.00
\$ 400.00
\$ 90.00
\$ 180.00
\$ 360.00
\$ 90.00
N/A
\$ 180.00
\$ 720.00
\$ 90.00
\$ 90.00
\$ 180.00
\$ 180.00
\$ 180.00
\$ 180.00

\$ 90.00
\$ 18,850.00 \$ 42,889.95

N/A
\$ 400.00
\$ 360.00
N/A
N/A
\$ 1,800.00
\$ 3,600.00
\$ 1,080.00